OIPE
FEB 0 8 2006
PATENT & TRADEMARK OFFICE
IAP19

PATENT
Docket No. 20004/3US

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Daniel Nelson

Serial No.: 10/047,734

Filed: November 9, 2001

For: APPARATUS AND METHOD FOR DETECTING AND CORRECTING A CORRUPTED BROADCAST TIME CODE

Group Art Unit: 2133

Examiner: F. Alphonse

I hereby certify that this paper is being deposited with the United States Postal Service with sufficient postage via first class mail in an envelope addressed to Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on this date

February 6, 2006

Mark G. Hanley
Registration No. 44, 736
Attorney for Applicant(s)

LETTER TO THE DRAFTSMAN

Commissioner for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450

Sir:

Applicant is submitting attached to this paper a replacement drawing for FIG. 2 in above mentioned application. In the replacement drawing, the lead line for the temporary memory buffer 37 is extended from the box next to the memory device 35 instead of the processor 32. Applicant respectfully submits that this modification corrects an error in the drawing and does not add any new matter. Applicant respectfully requests entry of this replacement drawing.

Respectfully submitted,

HANLEY, FLIGHT, & ZIMMERMAN, LLC
Suite 4220
20 North Wacker Drive
Chicago, Illinois 60606
(312) 580-1588

By: 
Mark G. Hanley
Registration No. 44, 736

February 6, 2006